

## Safety Compliant Breakaway Pole Base



1.) Radarsign driver feedback sign in East Park subdivision in Marietta, GA prior to impact by a hit and run driver.



3.) Radarsign's pole base broke away from the sign pole on impact as it was designed to do.



2.) The City of Marietta Police investigated the incident. It was estimated that the vehicle was traveling approximately 40-50MPH in a 25 MPH zone when it crossed lanes and struck the radar speed sign.



4.) The radar speed sign sustained minimal cosmetic damage to the YOUR SPEED faceplate. The radar speed sign and solar panel remained operational and intact.